



## **Technical Bulletin**

Date Released: 9-26-2007

Tracking Number: TBJHD1510-001

Model / Part Number JHD1510 / JHD3510

Re: Updating from JHD1000, JHD2000, JHD3000 – Fuse requirements

### **Details:**

When replacing older JHD radios with current JHD1510 / JHD3510 radios, the original harness may be used provided the switched line 1A fuse is replaced with a 15A fuse.

